

# SAILOR

Service Information No. 68  
Kundendienst-Mitteilung No.  
Service Information No.  
Información de servicio No.  
Servicemeddelelse No.


Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato

Re.: Transmitters T121, T124, T126 and T128

If the 18 V supply in the power supplies for the mentioned transmitters is faulty, please check if the fault is caused by the screen plate below the SSB generator.

It is recommended to cut the screen plate so that the possibility for short circuit of the 18 V supply is eliminated.



Please file this information in the service-portfolio we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.

**S. P. RADIC**  
Aalborg - Denmark