

SAILOR

Service Information No.
Kundendienst-Mitteilung No.
Service Information No. 70
Información de servicio No.
Servicemeddelelse No.

Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato

March, 1979

Modification of IF-Amplifier in SAILOR VHF RT143.

The modification has been made from series No. 174547.

Owing to delivery troubles in connection with TAA350A from Philips, we have had to find another supplier.

To replace TAA350A we have decided for CA3011 from RCA, which has the same electrical data but, unfortunately, a different pin position, which has involved a minor alteration of the print.

At repairs of the IF-Amplifier, in which IC201 or IC202 is defective, please observe whether a TAA350A or a CA3011 is mounted.

The tuning-up procedure is unaltered the same.

TAA350A for repairs will of course still be available from us.

In case a new IF-Amplifier module is ordered, it will be equipped with CA3011.

Encl.: Diagram

Parts List



Please file this information in the service-portfolio we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.

S. P. RADIC
Aalborg - Denmark