

# SAILOR

Service Information No. 78  
Kundendienst-Mitteilung No.  
Service Information No.  
Información de servicio No.  
Servicemeddelelse No.

Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato April, 1981

Conc. modification of the aerial circuit for the transmitters T1127, T1127L and T1127 with manual tuning of 2182 (Holland).

In order to make the aerial circuit in the mentioned three transmitters identical and thus permitting the mounting of H1201 (500 kHz tuner) outside the factory, the mentioned aerial circuit has been modified in all transmitters with a serial number higher than 201206.

As a result of the modification the tunint-up procedure for the bands 1,6 - 4 MHz has been altered a trifle.

In order to avoid misunderstandings all transmitters with a serial number higher than 201206 will be clearly marked, which also relates to the instruction manuals for transmitters with a serial number higher than 201206.



Please file this information in the service-portfolie we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous

a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.

A/S S. P. RADIO

Aalborg - Denmark