

SAILOR

Service Information No. 60
Kundendienst-Mitteilung No.
Service Information No.
Información de servicio No.
Servicemeddelelse No.

Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato October, 1974

INSTRUCTION MANUAL FOR SAILOR VHF RT143.

In the above mentioned instruction manual we have to our regret ascertained a misprint, which is of importance for the tuning-up of the frequency.

In the paragraph ADJUSTMENT AT RECEIVER CHASSIS on page 31 has been printed by mistake:

08 12141166 Hz C565 ± 12 Hz

which is to be altered to:

08 12141666 Hz C565 ± 12 Hz

INSTRUKTIONSBUCH FÜR SAILOR UKW RT143.

In dem oben erwähnten Instruktionsbuch haben wir leider einen Druckfehler festgestellt, der bei der Abgleichung der Frequenz von Bedeutung ist.

Im Abschnitt ABGLEICH-JUSTERUNGEN AN EMPFÄNGER auf Seite 31 hat man aus Versehen gedruckt:

08 12141166 Hz C565 ± 12 Hz

welches auf:

08 12141666 Hz C565 ± 12 Hz

zu ändern ist.

Please file this information in the service-portfolie we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.



S. P. RADIO

Aalborg - Denmark