





MOUNTING INSTRUCTION FOR SAILOR H1216



Outer screen must not be connected to ground.



Screens must be soldered to tinplate

Parts list for H1216

Symbol	Description	Manufact.	
	Aerial sockets	K.V.Hansen	S0239
Resistor	600 kohm <u>+10%</u> 2W	Rosenthal	LCA0933