

Service Information



JULY 2000

NUMBER 182

SAILOR PROGRAMME 2000 MF/HF SSB

Subject:

New software release.

Identification:

A new software version has recently been released for the Sailor RE2100 MF/HF controller.

This new release has been designated version **C1086U** (checksum 4D46).

Programmed eprom is available under the following part number:

RE2100 software prom - p/n **726166**

This software release implements a change in the default transmission mode of the 2182kHz distress alarm alert from H3E to J3E mode.

New equipment shipped from the factory after June 1st 2000 will have this software version installed. Updated status marked by revision letter C on rear of equipment.

Action:

This software change is not mandatory and hence need only be applied as required.

However, in case the Sailor RM2150 DSC Watch Receiver comprised in a Programme 2000 MF/HF SSB installation is replaced by a Sailor RM2152 DSC/Telex Modem, the Sailor RE2100 software should be updated to this latest release.

S.P. RADIO A/S • PORSVEJ 2 • DK-9200 AALBORG SV • DENMARK
PHONE INT. +45 96 34 61 00 • TELEX 69 789 SPRAD DK • TELEFAX INT. +45 96 34 61 01
E-MAIL: SAILOR@SAILOR.DK • WEB: WWW.SAILOR.DK

Charges:

Not applicable!

Estimated time required for installing new software prom and for verifying proper operation is 30 minutes.

Best regards,
S.P. Radio A/S

A handwritten signature in blue ink that reads "Dan Vestergaard". The signature is stylized with a large, sweeping initial "D" and a circular flourish at the end.

Dan Vestergaard
Service