

# SAILOR

Service Information No. 43  
Kundendienst-Mitteilung No.  
Service Information No.  
Información de servicio No.  
Servicemeddelelse No.

Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato May, 1972.

We hereby point out to you that we have altered the trimming procedure for the transmitter of SAILOR VHF RT141/RT142 and SAILOR VHF RT141/29 and RT142/29 from no. 93720.

We therefore kindly ask you to use the new trimming procedure described in the instruction manual, service-section page 15, when trimming transmitters from no. 93720 and on.

Yours faithfully,

S.P. RADIO A/S

Encl.: Service-section page 15 from the instruction manual  
Main-diagram of SAILOR VHF RT142  
Main-diagram of SAILOR VHF RT142/29



Please file this information in the service-portfolio we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous

a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.

S. P. RADIO  
Aalborg - Denmark