

SAILOR

Service Information No. 62
Kundendienst-Mitteilung No.
Service Information No.
Información de servicio No.
Servicemeddelelse No.

Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato 7th February 1975

Conc. Ferrite Direction Finder 46BK (old model) in connection with the RECEIVER R108.


Normally the ferrite direction finder BK171 is to be used in combination with the receiver R108.

However, if the situation calls for it, it will be possible to use 46BK in combination with R108, but in that case no sensing facilities will be available.

If 46BK is to be connected to the receiver, a new plug must be mounted on the ferrite direction finder.

The plug to be used is a Hirschmann MES 60BZ (which can be required from us).

The below sketch is showing the mounting.



Obs.! It will not be possible to use the new ferrite direction finder BK171 in combination with the receiver 46T.



Please file this information in the service-portfolio we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.

S. P. RADIO
Aalborg - Denmark