

SAILOR

Service Information No. 79
Kundendienst-Mitteilung No.
Service Information No.
Información de servicio No.
Servicemeddelelse No.

Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato August, 1981

Our main receiver SAILOR R1120 has until now been equipped with a supplementary filter for the reception of Lower Side Band (LSB).

From our agents we know that there is very little interest in receiving LSB, for which reason we have decided to remove the LSB filter and to alter the text on the front panel from LSB to AUX.

If a customer should want to be able to receive LSB signals or if he should want a special narrow filter for the reception of telex signals, such filters can be mounted on request.



Please file this information in the service-portfolio we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.

A/S S. P. RADIC
Aalborg - Denmark