

SAILOR

Service Information No.
Kundendienst-Mitteilung No.
Service Information No.
Información de servicio No.
Servicemeddelelse No.

93

Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato

June, 1985

DISPLAY R1119 - R1120 - S1303 - S1304

We have observed that errors in the display of the above mentioned units are occurring frequently.

The errors is due to an interruption of the back plan and the read-out will show nothing but the figures 8.

The error does not influence the other functions of the set.

When you have replaced the display you may return it to us for your credit.

=====

DISPLAY R1119 - R1120 - S1303 - S1304

Vi har observeret en øget fejlhyppighed på displayet i de ovennævnte enheder.

Fejlen skyldes en afbrydelse af backplanen, og udlæsningen bliver ene 8-taller.

Fejlen har ingen indflydelse på apparatets øvrige funktioner.

Efter udskiftning af displayet, er De velkommen til at sende det defekte til os for kreditering.



Please file this information in the service-portfolio we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.

=====

^{A/S} S. P. RADIO

Aalborg - Denmark

=====