

SAILOR

Service Information No. 106A
Kundendienst-Mitteilung No.
Service Information No.
Información de servicio No.
Servicemeddelelse No.

Series / Serie / Numéro de série / Serie / Serie

Date / Datum / Date / Fecha / Dato

October 1989

Vedrørende Prom'er type MMI 63S080 og type MMI 63S081

Ovennævnte prom'er er udgået af produktion, og fremover vil i stedet blive anvendt en NATIONAL type h.h.v. 74S188 og 74S288.

De nye typer bibeholder de gamle S.P. lagernumre på h.h.v. 32.742 for 74S188 og 32.750 for 74S288.

Skal de nye typer programmeres i prom-programmer SAILOR H233, skal denne sættes i stilling NATIONAL.

NB: Prom type AM27S19, der desværre er fejllleveret i et mindre antal, kan ikke programmeres med prom-programmer SAILOR H233.

Re.: Proms type MMI 63S080 and type MMI 63S081

The above-mentioned proms have been omitted from our production and in the future a NATIONAL type of 74S188 and 74S288 respectively will be used.

The new types keep the old S.P. stock numbers, 32.742 for 74S188 and 32.750 for 74S288 respectively.

If the new types are to be programmed in prom-programmer SAILOR H233, this unit must be in position NATIONAL.

NB: Prom type AM27S19, which unfortunately has been supplied by mistake in a small number, cannot be programmed with prom-programmer SAILOR H233.



Please file this information in the service-portfolie we have sent you.

Bitte archivieren Sie diese Mitteilung in der Kundendienstmappe, die wir Ihnen gesandt haben.

Nous vous prions de bien vouloir classer ce document dans le dossier bleu qui vous a été envoyé à cet effet.

Sivanse archivar esta información en la cubierta de servicio que les hemos enviado a Ustedes.

De bedes venligst arkivere denne meddelelse i den tilsendte servicemappe.

⌘ S. P. RADIO
Aalborg - Denmark