


Product: CH 2430 and P 7200



Technical Information

SUBJECT: Service replacement of Battery Charger CH 2430 and Power Supply P 7200.

To limit the repair time on the above mentioned products, Skanti has decided that the units must be returned for repair as complete items.

To make it more convenient for the customers and for the Service Agents, Skanti has also decided to include the two items in the exchange programme.

The part numbers for the restored units are as follows:

CH 2430	R31924
P 7200	R1088002

When a unit is returned to Skanti for exchange/repair please be advised that you might receive a new/restored unit with a different serial number.

For further information, kindly contact the SKANTI service department.